


T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 13 Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees	
	R. OAK	R. OAK
Diameter	<u>8"</u>	<u>7"</u>
Bearing	<u>N 31 E</u>	<u>S 40 1/2 W</u>
Distance	<u>23 LKS</u>	<u>23 LKS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1912 By M.A. KEMP
Location filed COUNTY BOOK " 1.54
Monument FND 4X4X60" WOOD STAKE - AND ^{POSSIBLE} GOUT B.T.
STUMP 7" R. OAK S 40 1/2 W 23 LKS. CORNER IS ACTUALLY
N 45 W 18" - SET 2X2X20" OAK STAKE FROM STUMP
WITH IRON MARKS.

Evidence of Subsequent Corner Restoration

Year of search 1917 By GLO
FND OLD WOOD STAKE AND BOTH GOUT B.T. STUMPS
1/4 - S 12
513
1917

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

<u>N. PINE</u>	<u>W. OAK</u>
<u>14"</u>	<u>14"</u>
<u>N 41 W</u>	<u>S 14 3/4 W</u>
<u>106 LKS</u>	<u>149 LKS</u>

Subsequent Corner Restoration

Year surveyed 1999 By CCSO
Location filed Cass Co.
Monument Monument fnd. in place but bent.
Re-set ~~was~~ existing 1" OD IP x 24" with two
fnd. B.T.'s. Located 11' N E C.R. 124.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

REF. TIES:

* <u>8" R. Oak</u>	<u>N 37° W</u>	<u>103.07'</u>
<u>6" W. Oak</u>	<u>S 60° W</u>	<u>97.38'</u>
* <u>17" W. Oak</u>	<u>N 68° E</u>	<u>138.14'</u>
<u>BT Pine Snag</u>	<u>S 38° E</u>	<u>121.57' fnd.</u>
<u>BT 14" W. Oak</u>	<u>N 44° E</u>	<u>156.72' fnd.</u>

* distance pulled to dbl. hd. nail