


Index No. L17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 15 Corner common to sections 14, 15



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POPLAR</u>	<u>POPLAR</u>	
<u>10"</u>	<u>8"</u>	
<u>524E</u>	<u>550W</u>	
<u>20 LKS</u>	<u>10 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed SEC. OF STATE
Monument SET 1x36" I.P. w/ BEARS CAP PROPORTIONALLY
1/4
515 / 514
1917

Evidence of Subsequent Corner Restoration

Year of search 1962 By Pete Meyer
Found GLO monument in good condition;
6" Poplar N 67 1/4 E 33.34' now stump; 12"
Poplar N 39 1/4 W 108.24' now 17"

Species	Bearing	Trees, Reference Objects
<u>POPLAR</u>	<u>POPLAR</u>	
<u>6"</u>	<u>12"</u>	
<u>N 67 1/4 E</u>	<u>N 39 1/4 W</u>	
<u>49 LKS</u>	<u>164 LKS</u>	

Bearing Trees, Reference Objects

Tamarack	W. Pine	Oak
<u>15"</u>	<u>8"</u>	<u>8"</u>
<u>560 1/2 E</u>	<u>568 W</u>	<u>N 18 W</u>
<u>88.90'</u>	<u>80.6'</u>	<u>61.0'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____