


Index No. R7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 29 Corner common to sections 29, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>OAK</u>	<u>OAK</u>
Diameter	<u>12"</u>	<u>14"</u>
Bearing	<u>N70W</u>	<u>S38W</u>
Distance	<u>96 LKS</u>	<u>30 LKS</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 5' aluminum rod with aluminum cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

	<u>Poplar</u>	<u>Maple</u>	<u>Burr Oak</u>
Species			
Diameter	<u>6"</u>	<u>14"</u>	<u>10"</u>
Bearing	<u>S73W</u>	<u>S45W</u>	<u>S83E</u>
Distance	<u>45.38'</u>	<u>57.93'</u>	<u>77.47'</u>

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 311064

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_