


Index No. T5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument POST

**Bearing Trees**  
 Species PINE SPRUCE  
 Diameter 10" 5"  
 Bearing N65W S18 1/2 E  
 Distance 26 LKS 23 LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1922 By E. B. HORST  
 Location filed COUNTY RESURVEY "E-38"  
 Monument IRON MONUMENT  
1922, E. B. HORST, BOOK C' P 469 SET 2x40" ILM

**Evidence of Subsequent Corner Restoration**  
 Year of search 1988 By David Landecker  
Set 10' aluminum rod with aluminum cap.

**Bearing Trees, Reference Objects**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**

<u>Burr Oak</u>	<u>J. Pine</u>	<u>Birch</u>	<u>2 1/2"</u>
<u>18"</u>	<u>9"</u>	<u>6"</u>	<u>Iron Pipe</u>
<u>S40W</u>	<u>S26W</u>	<u>S14E</u>	<u>N10 5/8 26 W</u>
<u>124.94'</u>	<u>128.79'</u>	<u>129.96'</u>	<u>39.32'</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 31870

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_