


Index No. X 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 32 Corner common to sections 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>R. OAK</u>	<u>POPULAR</u>	
Diameter <u>10"</u>	<u>12"</u>	
Bearing <u>N77 1/2 E</u>	<u>N73W</u>	
Distance <u>19 LKS</u>	<u>75 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landscker  
Location filed \_\_\_\_\_  
Monument Set 2" x 54" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Trees, Reference Objects
<u>Burr Oak</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
Diameter <u>8"</u>	<u>10"</u>	<u>7"</u>
Bearing <u>N10W</u>	<u>N30E</u>	<u>S72E</u>
Distance <u>35.29'</u>	<u>42.59'</u>	<u>28.76'</u>

Bearing Trees, Reference Objects

Species	Bearing	Trees, Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1989 Certificate - David Landscker  
Doc. # 311182

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_