


T. 141 R. 31 M. 5th Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search 1915 by Scott
Monument found _____
Curo Book 78, page 60

Bearing Trees

Species	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>
Diameter	<u>12"</u>	<u>36"</u>	<u>24"</u>	<u>24"</u>
Bearing	<u>N 33° E</u>	<u>N 58° W</u>	<u>S 8° W</u>	<u>S 40° E</u>
Distance	<u>94 links</u>	<u>30 links</u>	<u>49 links</u>	<u>55 links</u>

Original Bearing Trees Found

Species	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 8/1915 By P.M. Scott
Location filed: Survey Record #491, Book C, page 575 and Curo Monument: 2" Square post Curo Book 58, images 102, 111-112, 152 found corner set by Curo and set iron monument at corner.

Evidence of Subsequent Corner Restoration

Year of search 9/1915 By P.M. Scott
Location filed: Curo Book 78, page 60
Monument: With Curo go to Section 7-141-31 and set N.E. cor. finding true bearing trees.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/1915 By J.W. Curo, LS 1428
Location filed: Section resurvey, Curo contract #12
Monument: Known corner corner set from old bearing trees.

Evidence of Subsequent Corner Restoration Found

Year of search 12/1958 By H.J. Curo, LS 3417
Location filed: Curo Book 307, page 7
Monument: Found 2.5" ODIP with cap on top 18" Norway Pine, S 78°20' E, 42.30' 6" Red Oak, N 18°52' E, 19.60' 9" Red Oak, N 79°55' W, 20.00'

5/1916, F.F. Wilson Curo Book 86, pages 8 and 22 Found iron pipe, set by County Surveyor, Curo.
2/1931, R.A. Dahms, LS 936 Ditch Shelf 1, Book 158, page 30 Indicates iron pipe at the SE corner of Section 6.
2/1942, J.W. Curo, LS 1428 Svey Record #590, Book D, page 284 Found 2" iron pipe set by me and witnessed as follows: 12" Red Oak, N 27°45' E, 63.40' to spot at base of tree 6" Red Oak, N 85° W, 20.05' to spot at base of tree 4" W. Oak, S 32°10' W, 13.10' to spot at base of tree 16" Norway Pine, S 82°30' E, 41.60' to spot at base of tree

6/1978, C.R. Krause, USFS USFS Book 1, page 29 Found 2.5" ODIP set by Curo and replaced it with USFS brass cap monument and reset Curo pipe beside new monument, piled rocks around pipes and witnessed. 23" Norway Pine, S 80° E, 41.55'(1942) rescribed 6" W. Oak, S 35° W, 13.22'(1942) rescribed 7" Red Oak, N 40° W, 33.18' blazed 7" W. Oak, N 41° E, 67.43' blazed Steel Sign Post, South, 4.0'

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 8/1984 By W.H. Okerman, LS 6807

Year of search _____ By _____

Location filed: Certificate of Location

Location filed:

Monument: Found USFS brass cap in stone mound and witnessed.

Monument:

23" Norway Pine, S 79° E, 42.08'(1942)

6" W. Oak, S 38° W, 13.20'(1942)

10" Red Oak, N 78° W, 20.04'(1942)

15" Red Oak, N 33° E, 63.93'(1942)

9" Red Oak, N 22° E, 19.80'(1958)

7" Red Oak, N 38° W, 33.18'(1978)

8" White Oak, N 46° E, 67.43' (1978)

Steel Sign Post, South, 3.90'(1978)

Steel Sign Post, East, 3.73'

11/2018, CCHD/SO

#2018.005

Found USFS brass cap, up 1.6' and 2" ODIP with plumber cap adjacent on NW side, in stone mound, on top of hill.

24" N. Pine, S 79° E, 42.16'(1942) duplex nail, up 1.0', N. side

10" B. Oak, S 35° W, 13.22'(1942) 20d spike, up 1.4', E. side

12" Red Oak, N 22° E, 19.80'(1958) 20d spike, up 0.7', E. side

12" W. Oak, N 46° E, 67.43' (1978) 20d spike, up 1.0', N. side

8" B. Oak, N 80° W, 35.62' duplex nail, up 1.0', N. side


Steel Sign Post, South, 4.0'(1978)

Steel Sign Post, East, 3.9'(1984)

Index No. E5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	W. PINE	W. PINE	W. PINE	W. PINE
Diameter	12"	36"	24"	24"
Bearing	N33E	N58W	SBW	S40E
Distance	94LKS	30LKS	49LKS	55LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO
Location filed COUNTY RESURVEY PLAT "E-51"
Monument 2 1/4 x 48" IRON MONUMENT
1915 SCOTT, BOOK "C" P. 575 FND CORNER SET BY CURO
P. 579 SET I.P. FROM TRUE BEARING TREES
also on microfilm - roll 105 BK 58 P. 27, 71(86)

Evidence of Subsequent Corner Restoration

Year of search 1942 By JOHN CURO
COUNTY BOOK "D" P. 284, JOHN CURO FND 2" I.P.
SET PREVIOUSLY FROM GOVT BATS

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>also on microfilm - roll 115 BK 78 P. 60</u>			

Bearing Trees, Reference Objects

R. OAK	R. OAK	W. OAK	N. PINE
12"	6"	4"	16"
N27-45E	N85W	S32-10W	S82-30E
63.40'	20.05'	13.10'	41.60'
1942 TIES DOUBLES BLAZES ON BATS.			

Subsequent Corner Restoration

Year surveyed 1916 By F. F. Wilson
Location filed microfilm - roll 115 BK 86 P. 9
Monument Fnd iron monument previously established

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1958
Certificate - Bill OKerman - 1985
Doc. # 280552

1984 - Certificate - Bill OKerman
Fnd 2 1/2 x 60" pipe w/ 3" brass cap set in
1978 by USFS. This pipe replaced 2 1/2 x 48"
capped I.P. set in 1915 by John Curo.
W. oak 6" S38W 13.20' } 1942 ties
R. oak 10" N78W 20.04' }
R. oak 15" N33E 63.93' }
N. Pine 23" S79E 42.08' }
R. oak 9" N22E 19.80' 1958 tie
R. oak 7" N38W 33.18' ? 1978
W. oak 8" N46E 67.43' } ties.

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____