


Index No. F4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5th Coordinates: X _____ Y _____
NE 1/4 Corner common to sections 7



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer
Location filed _____
Monument Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Tamarack Elm
Diameter 18" 13"
Bearing S 38E N 1/2 W
Distance 84.3' 8.6'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962
Aug 2003 T. Miller #23046
Govt. of Sux. shows Mon. found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____