


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
M.C. # 28 Corner common to sections 7, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ELM WILLOW
Diameter 4" 14"
Bearing S7E S40W
Distance 9 LKS 72 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN Curo
Location filed COUNTY RESURVEY PLAT "E-51"
Monument 2 1/4 x 4 1/8" IRON MONUMENT FOR WC 1/4
176' S. of 1/4
also on microfilm - Scott Roll 105 BK58
P. 76 (91)

Evidence of Subsequent Corner Restoration

Year of search 1984 By Bill Okerman
Corner Certificate
Find I.P. set for WC 1/4.
Set new 2 1/2" I.P. w/ 3" brass cap for M.C.
at lost position

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>W oak</u>	<u>Ash</u>	<u>Ash</u>
<u>8"</u>	<u>12"</u>	<u>7"</u>
<u>N21E</u>	<u>S7W</u>	<u>S82W</u>
<u>9.37'</u>	<u>7.79'</u>	<u>36.21'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Harold Curo - 1959
Certificate - Bill Okerman - 1985
Doc. # 280562