


T. 141 R. 31 M. 5TH Coordinates: X E 1/4 25 Y 25 AND 30-141-30
Corner common to sections 25 AND 30-141-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>ASPEN</u>	Bearing Trees	<u>5.67E MAPLE</u>
Diameter	<u>6"</u>		<u>5"</u>
Bearing	<u>S 37 E</u>		<u>S 30 W</u>
Distance	<u>44.85</u>		<u>10.65</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By E.B. HORST
Location filed COUNTY RESURVEY "E-38"
Monument Iron Monument
1921, E.B. Horst, County Resurvey "E-33" I.M.
1920, E.B. Horst, Book "C" 1464 SET I.M.
also on microfilm - roll 115 BK 80 P. 122, 143

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker
Set 2" x 24" iron monument with brass cap.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>Birch</u>	<u>Burr Oak</u>	<u>1" iron</u>
<u>7"</u>	<u>6"</u>	<u>6"</u>	<u>PIPE</u>
<u>S 2 W</u>	<u>S 86 E</u>	<u>N 68 E</u>	<u>N 11 E</u>
<u>85.40'</u>	<u>85.67'</u>	<u>67.65'</u>	<u>5.41'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 310684

July 2003; m. landecker # 7452
Cert. of Survey shows corner found