


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
N1/4 34 Corner common to sections 27, 34



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Bearing Trees
 Species MAPLE IRONWOOD
 Diameter 5" 4"
 Bearing S17W N23E
 Distance 18LKS 19LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1928 By JOHN GREENE
 Location filed COUNTY RESURVEY PLAT E-55'
 Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration
 Year of search 1987 By WALT Curo
 Corner Certificate - Doc # 302147
Fnd 2 3/4" (1 IP w) cap as per 1959 Certificate

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
Burr oak Burr oak Burr oak
14" 8" 10"
N17W N53W S34W
45.25' 36.54' 34.85'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - HAROLD Curo - 1959
Certificate - Walt Curo - 1987
OCT. 2000 - CCSD
Fnd. in place; 2" IP w/ brass cap up
1.7' RLS No. 3417 (1959)
 REF. TIES:
9" W. Oak N 5° W 45.18' (fnd. B.T.)
8" W. Oak N 45° W 36.52' (fnd. B.T.)
7" W. oak S 40° W 34.79' (fnd. B.T.)
10" W. Pine N 49° E 41.84'
Land Mon. sign post SOUTH 4.6'
" " EAST 3.3' (bent & sign gone)