


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
SW 31 Corner common to sections 31 W.C. 2.50 ch. North.



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1871
 Original monument POST FOR W.C. 2.50 ch. North

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species Aspen Pine
 Diameter 7 7
 Bearing N16W N82E
 Distance 69 lks 88 lks

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1921 By E. B. Horst
 Location filed COUNTY RESURVEY PLAT "E-55"
 Monument W.C. 165' NORTH IRON MONUMENT
1921, E. B. Horst, Book "C" P445 Fwd 2 1/2 x 48" I.M.
CORNER IS A WOOD POST IN B.G.

Evidence of Subsequent Corner Restoration Found
 Year of search 1984 By Tony Kerick
Corner Certificate
Find 3" brass cap monument set in 1959 by
Harold Curo, stamped the cap 165' N. ↓

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>R.oak</u>	<u>W.oak</u>	<u>R.oak</u>	<u>Cedar Post</u>	<u>Charred cedar post</u>
<u>12"</u>	<u>8"</u>	<u>5"</u>	<u>4x4</u>	<u>4x4</u>
<u>N11W</u>	<u>N37E</u>	<u>N49E</u>	<u>N56W</u>	<u>N22E</u>
<u>145.41'</u>	<u>59.30'</u>	<u>53.80'</u>	<u>23.99'</u>	<u>24.03'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1959
Certificate - Tony Kerick - 1984
Doc. # 280497