


Index No. U 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 57H Coordinates: X _____ Y _____
5/16 Corner common to sections 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument Set 2" x 24" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search 8/2000 By CCSO
Corner destroyed by road const.
Set 7/8" ODIP at calc. position from
Hwy. Dept. info. 28'± W. of & CR#52,
21'± N. of Driveway.

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>18"</u>	<u>6"</u>	<u>7"</u>
Bearing	<u>N15W</u>	<u>N50W</u>	<u>N75W</u>
Distance	<u>133.87'</u>	<u>105.33'</u>	<u>106.98'</u>

Bearing Trees, Reference Objects

P. Pole
S 20° W
84.85'*
*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALT Curo - 1982
Doc. # 261628

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____