


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>MAPLE</u>	<u>FIR</u>
Diameter <u>8"</u>	<u>6"</u>
Bearing <u>S78E</u>	<u>N70W</u>
Distance <u>6 LBS</u>	<u>13 LBS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN
Location filed COUNTY BOOK "C" P 416
Monument CORNER IN Q OF HWY.
COUNTY RESURVEY 1921 "E-2" T.M.

Evidence of Subsequent Corner Restoration

Year of search 1982 By G. HWY & SURVEYOR
FIND NOTHING.

1986 - Walt Curo Set Corner - 2" x 24" galv.
1 1/2" w/ brass cap.

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

<u>W. oak</u>	<u>Power Pole</u>	<u>Tele. Box</u>
<u>4"</u>	<u>N50°W</u>	<u>Guard Post</u>
<u>N20°W</u>	<u>81.83'</u>	<u>S45°W</u>
<u>52.06'</u>		<u>64.73'</u>

V-19

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument CORNER GPS 4/4/03 CCSSO
CCSSO 4/4/03 Found brass cap near
Flush, 1' ± S. of E cor. rd. #4
1986 witnesses are good.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo 1986
Doc. # 291471