

Index No. \_\_\_\_\_

### CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

#### EXISTING SURVEYS

##### Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument \_\_\_\_\_

##### Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
 Monument found \_\_\_\_\_

##### Bearing Trees

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_


##### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

T. 142 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 35 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Tree
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>S50W</u>	<u>S52E</u>	
Distance <u>6 LKS</u>	<u>75 LKS</u>	

Species	Bearing	Tree
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1912 By JAMES FLYNN  
Location filed COUNTY BOOK "B" P 514-515  
Monument FIND OLD GOVT BIT: 10' ASPEN S52E 79 LKS

Evidence of Subsequent Corner Restoration

Year of search 1982 By Co. Hwy. & Surveyor  
Found 1/2" IRON ROD WITH 1x2" SOLID OVAL HEAD.  
DOWN 2.4', TOP 6" BENT OVER. IN LINE WITH FENCE  
WEST - STARTS ± 500' WEST ± 7' SOUTH OF FENCE  
EAST LINE N-S Co. RD #4.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. OAK</u>	<u>BALSAM</u>	<u>C.F.P.</u>
<u>4"</u>	<u>6"</u>	
<u>S52E</u>	<u>S80E</u>	<u>N79E</u>
<u>79.25'</u>	<u>91.34</u>	<u>46.58'</u>

X-21

Subsequent Corner Restoration

Year surveyed 2000 By CCSO  
Location filed CCSO  
Monument Brass cap monument, flush in E, 1986 witnesses cut for power line. Add the following:  
P. Pole, N31°E, 107.62\* tag  
6" Maple, S88°E, 91.55\*  
8" W. Pine, S47°E, 134.45\*

\* denotes double headed nail

Evidence of Subsequent Corner Restoration Found

Year of search 1986 By \_\_\_\_\_  
Certificate - Walt Curo - 1986  
Doc. # 291474  
Found 1/2" w/oval head down 2.3' set 2"x24"  
galv. 1/4" w/brass cap  
Power Pole N15°E 150.52'  
6" Aspen EAST 72.77'  
4" W. Oak S55E 79.23'

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_