


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34-143-27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

	Bearing	Trees	
Species	<u>SPRUCE</u>	<u>SPRUCE</u>	<u>SPRUCE</u>
Diameter	<u>5"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>S47E</u>	<u>S22W</u>	<u>N9W</u>
Distance	<u>3545</u>	<u>2345</u>	<u>3645</u>

Original Evidence Found

Year of search 1940 By CCC

Monument found POST
REPLACED WITH IRON PIPE

Original Bearing Trees Found

Species	<u>TAMARACK</u>	<u>TAMARACK</u>
Diameter	<u>10"</u>	<u>8"</u>
Bearing	<u>N9°W</u>	<u>N55°E</u>
Distance	<u>361ks</u>	<u>381ks</u>

Subsequent Corner Restoration

Year surveyed 1903 By CORPS OF ENG

Location filed _____

Monument 2 - TAMs 1 - SPRUCE STANDING LINE

Evidence of Subsequent Corner Restoration

Year of search APRIL 1999 By L. LEVELLING #16089
REPLACED A FOUND 1" IRON PIPE WITH AN ALUMINUM CAPPED ALUMINUM ROD CERT OF LOCATION DOC. # 412251

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

GLO STUMP 0.120 TAM 0.170 B. SPRUCE 0.110 TAM

<u>N 9° W</u>	<u>N 71° W</u>	<u>S 42° E</u>	<u>S 37° W</u>
<u>6.490 m</u>	<u>5.998 m</u>	<u>8.864 m</u>	<u>8.986 m</u>

Subsequent Corner Restoration

Year surveyed 1970 By USFS - KRAUSE

Location filed _____

Monument FOUND 1" x 24" IRON PIPE & POINTED 1" x 1" WOOD STAKE & PS LOCATION POSTER ON:
5" SPRUCE SW 1.615 m

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____