


Index No. A 15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
N 114 3 Corner common to sections 3 AND 34 - 143 - 27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Species	Bearing	Trees
<u>TAM.</u>	<u>TAM.</u>	
<u>6"</u>	<u>8"</u>	
<u>S 39 W</u>	<u>N 68 E</u>	
<u>18 LKS</u>	<u>20 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1999 By L. Leuelling RLS # 16089
set alum. capped, alum. rod based on
the Orig. 610 bearings and distances from
orig. B.T. evidence

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>CEDAR</u>	<u>6"</u>	<u>N 33° W</u>	<u>1.49'</u>
<u>BLK. SPRUCE</u>	<u>4"</u>	<u>S 84° E</u>	<u>4.49'</u>
<u>TAMARACK</u>	<u>10"</u>	<u>S 50° W</u>	<u>4.56'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
(Cont. from front)
8" Tamarack stump N 62° E 13.75' (1873)
10" " " S 35° W 12.47' (1873)
Steel signpost (FS 54-9) S 38° E 2.18'

CERT. OF LOCATION 5/25/99
DOC. # 413183

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____