


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
N 14 17 Corner common to sections 8, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument 5" Poplar

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees	
<u>Poplar</u>	<u>Poplar</u>	
Diameter <u>5"</u>	<u>5"</u>	
Bearing <u>N41W</u>	<u>S50E</u>	
Distance <u>23 LKS</u>	<u>8 LKS</u>	

Original Bearing Trees Found			
Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SEC. OF STATE
Monument NO ORIG. EVIDENCE SET 1X36" I.P.W/BRASS CAP PROPORTIONALLY.
1/4 S8
517
1919

Evidence of Subsequent Corner Restoration

Year of search 1979 By Gary Stevenson
Found GLO monument broken.
Set 2"x24" galvanized iron pipe with 3" marked brass cap.

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>5"</u>	<u>6"</u>
Bearing	<u>N10 1/2 E</u>	<u>S67 3/4 W</u>
Distance	<u>60 LKS</u>	<u>53 LKS</u>

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>W. Oak</u>	<u>W. Oak</u>	<u>N. Pine</u>
Diameter	<u>12"</u>	<u>15"</u>	<u>9"</u>
Bearing	<u>N40W</u>	<u>S48W</u>	<u>N2E</u>
Distance	<u>79.57'</u>	<u>120.28'</u>	<u>61.33'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264919