


Index No. V 12-13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
MC # 45 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species ASH

Diameter 7"

Bearing S38W

Distance 42 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By GLO

Location filed SEC. OF STATE

Monument SET 1/8" W BRASS CAP T 142 N
528/mc
SET 36" IN GROUND 533/
R2W
1919

Bearing Trees, Reference Objects

Species ELM W. OAK

Diameter 14" 12"

Bearing S23 3/4 W N72 3/4 W

Distance 43 LKS 90 LKS

Evidence of Subsequent Corner Restoration

Year of search 1983 6/20 By Co. Survey Tech. & USFS

Find NW 1917 B.T. still standing green - now 16"

July 12 - Co. Survey Tech T. Freeman & County Hwy Bridge
crew found 1917 brass cap monument down 4.2'
7.5' N of C - Bottom Flanges broken off - no sign
of them near monument twisted out of position.
reset mon. 2' below surface.

Bearing Trees, Reference Objects

w. oak NW end bridge SW end bridge

16" curb-brass disc curb-brass disc

278° 80° 108°

59.30' 44.20' 47.10'

brass disc S. side

57.7' to face

Subsequent Corner Restoration

Year surveyed 9/99 By CCSO

Location filed file # 99046

Monument Found & Located GLO Brass cap.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____