


Index No. W 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/16 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919  
Original monument 1 x 36" 1. P. W. BARS N 1/16 535/536  
Cap 1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species R. OAK DOUBLE MAPLE  
Diameter 26" 12"  
Bearing S 82 E S 25-15 W  
Distance 163 KFS 121 KFS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1928 By GLO  
Location filed SEC. OF STATE  
Monument CORNER WAS DESTROYED BY ROAD CONSTRUCTION -  
RESET COR FLUSH IN CENTER OF ROAD FROM B.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1932 By \_\_\_\_\_  
Co. DITCH SURVEY BK 173 BOX 3 OF  
Co. DITCH SURVEY BOOKS, PG 80

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_