


T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
1/64 Corner common to sections 9 & 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1"x36" I.P. w/Bk.Cap

APZ.  
TR.  
1905

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>OAK</u>	<u>OAK</u>	<u>Maple</u>
Diameter	<u>8"</u>	<u>24"</u>	<u>12"</u>
Bearing	<u>N85E</u>	<u>N52E</u>	<u>N68W</u>
Distance	<u>47.10'</u>	<u>56.80'</u>	<u>81.60'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN 1970  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_