


T. 142 R. 30 M. 574 Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>Oak</u>	<u>Poplar</u>	<u>Ash</u>	<u>Poplar</u>
Diameter	<u>3</u>	<u>14</u>	<u>5</u>	<u>6</u>
Bearing	<u>N18E</u>	<u>N75W</u>	<u>S12E</u>	<u>S62W</u>
Distance	<u>16 lks</u>	<u>112 lks</u>	<u>73 lks</u>	<u>80 lks</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument Feb. the point of old post and
remains of 4 original BTS - Set 2"x36" I.P.
w/ Br. Cap.

Evidence of Subsequent Corner Restoration

Year of search 1935 By GLO
Found monument and BTS as per 1918
Survey.

Bearing Trees, Reference Objects

Species	<u>W.Oak</u>	<u>Maple</u>	<u>W.Oak</u>
Diameter	<u>6</u>	<u>8</u>	<u>7</u>
Bearing	<u>S73 1/2 W</u>	<u>N72W</u>	<u>S31 1/4 E</u>
Distance	<u>105 lks</u>	<u>121 lks</u>	<u>243 lks</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Ockerman - 1970
Found GLO monument in good condition.
15" Elm N65W 71.00'