


T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
N 14 21 Corner common to sections 16, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Oak</u>	<u>Maple</u>	_____
Diameter	<u>16</u>	<u>16</u>	_____
Bearing	<u>S 16 E</u>	<u>N 31 E</u>	_____
Distance	<u>10 lks</u>	<u>34 lks</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument Set 1" x 36" I.P. w/ Br. Cap at
proportional point - no evidence of
original.

Evidence of Subsequent Corner Restoration

Year of search 1964 By Pete Meyer
Found GLO monument in good condition.
32" Pine N 22 3/4 E 25.08' now 34"; 6" Oak
S 43 1/4 W 47.5' now decayed stump.

Bearing Trees, Reference Objects

Species	<u>Pine</u>	<u>Oak</u>	_____
Diameter	<u>32</u>	<u>6</u>	_____
Bearing	<u>N 22 3/4 E</u>	<u>S 43 1/4 W</u>	_____
Distance	<u>38 lks</u>	<u>75 lks</u>	_____

Bearing Trees, Reference Objects

<u>W. Oak</u>	<u>Red Oak</u>	_____
<u>9"</u>	<u>10"</u>	_____
<u>S 27 1/2 W</u>	<u>N 79 W</u>	_____
<u>81.35'</u>	<u>69.9'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1964