


Index No. N7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
N1420 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>W. Pine</u>	<u>y. Pine</u>
Diameter <u>24"</u>	<u>10"</u>
Bearing <u>S35W</u>	<u>N84W</u>
Distance <u>420 lks</u>	<u>200 lks</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLC
Location filed _____
Monument Set 1" x 36" I.P. w/ Br. Cap at record distance; bearing - no evidence found of original

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman
Set 5 1/2 x 5 1/2 x 60" concrete monument with brass cap.

Bearing Trees, Reference Objects

Species	Elm	Episcopal Church South end	Mission School SW cor
<u>Pine</u>	<u>8</u>	<u>N6E</u>	<u>N67W</u>
Diameter <u>13</u>	<u>50-45W</u>	<u>14.94 ch.</u>	
Bearing <u>N73 1/2 E</u>			
Distance <u>148 lks</u>			

Bearing Trees, Reference Objects

Elm	Oak	Elm	Cedar post
<u>11"</u>	<u>6"</u>	<u>26"</u>	<u>6" x 6" x 96"</u>
<u>588E</u>	<u>560E</u>	<u>52E</u>	<u>East</u>
<u>113.70'</u>	<u>106.70'</u>	<u>77.40'</u>	<u>2.50'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1970

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____