


T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
NW 1/6 Corner common to sections 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1" x 3/8" I.P. w/Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Poplar</u>	<u>Poplar</u>	_____	_____
Diameter	<u>6</u>	<u>5</u>	_____	_____
Bearing	<u>S 17 1/4 E</u>	<u>S 23 SW</u>	_____	_____
Distance	<u>40 lks</u>	<u>44 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1964 By PETE MEYER
Location filed _____
Monument Found GLO monument in good condition. Both BT's are now stumps.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Red Pine</u>	<u>White Pine</u>	_____	_____
Diameter	<u>10"</u>	<u>11"</u>	_____	_____
Bearing	<u>N 85 W</u>	<u>N 35 E</u>	_____	_____
Distance	<u>19.1'</u>	<u>41.25'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1964