


Index No. T-5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
214 30 Corner common to sections 30:29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Tam Tam
Diameter 8 5
Bearing S49E S74W
Distance 54 lks 44 lks

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed _____
Monument Set 1" x 36" I.P. w / Br. cap from
remains of original BTS:
Tam. 6" S74W 44 lks
Dead & fallen Tam 8" S49E 54 lks

Evidence of Subsequent Corner Restoration

Year of search 1981 By Gary Stevenson
Found GLO monument in good condition.
Sept. 1911, Top rd order shows no survey

Bearing Trees, Reference Objects

Species Tam Tam
Diameter 6 6
Bearing N49 1/2 E S55W
Distance 42 lks 14 lks

Bearing Trees, Reference Objects

W. Oak Tamarack Tamarack
19" 10" 6"
N7E S85E S21W
267.06' 15.42' 32.05'

T-5

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1982
Doc. #264931
1999 - Landecker + Assoc.
Cert. of Survey shows a GLO
Brass cap monument found.
Aug 2003 T. Freeman #21367
Cert of Svy shows Mon Found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____