


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Species	Bearing	Trees	Distance
<u>Pine</u>	<u>Pine</u>	<u>Oak</u>	<u>Poplar</u>
<u>3</u>	<u>10</u>	<u>10</u>	<u>6</u>
<u>NSE</u>	<u>NSW</u>	<u>S12W</u>	<u>STE</u>
<u>37 lks</u>	<u>38 lks</u>	<u>152 lks</u>	<u>95 lks</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1917 By GLO
 Location filed _____
 Monument Set 2" x 36" L.P. w/ Br. Cap from stumps of 3 original BTS and 1 stump hole.

Evidence of Subsequent Corner Restoration
 Year of search 1999 By LANDECKER + ASSOC.
Cert. of Survey shows that a USFS brass cap monument was found.
11/03 Cert. shows Brass cap

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Pine</u>	<u>R. Oak</u>	_____
<u>5</u>	<u>10</u>	_____
<u>N69 1/4 E</u>	<u>S72 E</u>	_____
<u>216 lks</u>	<u>271 lks</u>	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search 2000 By CCSO
Ind. impl. USFS Brass Cap mon., dwn. 0.6' Located 8' west of 1/4 Rd. & E trail to the north.
REF. TIES:

<u>6" R. Oak</u>	<u>N 69° E</u>	<u>73.67'</u>
<u>10" W. Oak</u>	<u>S 34° E</u>	<u>64.65'</u>
<u>10" R. Oak</u>	<u>S 80° W</u>	<u>44.85'</u>
<u>Mon. sign post</u>	<u>N 45° W</u>	<u>29.90'</u>

Oct. 1914, Twp ord order shows no survey