


T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 18 Corner common to sections 7, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Poplar</u>	<u>Birch</u>	_____	_____
Diameter	<u>4</u>	<u>4</u>	_____	_____
Bearing	<u>N29W</u>	<u>S44W</u>	_____	_____
Distance	<u>18 lks</u>	<u>8 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO
 Location filed COUNTY RESURVEY PLAT "E-57"
 Monument IRON MONUMENT
1921, E.B. HORST, COUNTY RESURVEY PLAT "E-57" 2x40" I.M.
1915, E.B. HORST BOOK "C" P. 44 SET I.M.
1920, E.B. HORST, BOOK "C" P. 472 FND I.M. OLD B.T.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1915 By HORST
microfilm - roll 115 BK 78 P. 90
set I.M's at W 1/4, 1/4 and E 1/4

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - David Landecker
Doc # 327268
Found 2" iron pipe up 10". Set
aluminum cap on found 2" iron pipe
9" Burr Oak N46W 96.68'; 8" Burr Oak
N54E 31.90'; 6" Maple S39W 34.81'.