


T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
Ely 24 Corner common to sections 24 and 19-142-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Bearing Trees

Species	<u>J. Pine</u>	<u>Y. Pine</u>	_____
Diameter	<u>14"</u>	<u>8"</u>	_____
Bearing	<u>N 11 E</u>	<u>N 3 W</u>	_____
Distance	<u>55 lks</u>	<u>66 lks.</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed _____
Monument Set 1" x 36" l.P. w/ Br. Cap at proportional point - no evidence found of original. Corner in swamp.

Evidence of Subsequent Corner Restoration

Year of search 1986 By Robert Murray
Corner Certificate - Doc. # 296471
Find GLO brass cap monument and oak B.T SE
5' steel signpost west 30'

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Pine</u>	_____
Diameter	<u>10</u>	<u>12</u>	_____
Bearing	<u>S 16 E</u>	<u>S 69 W</u>	_____
Distance	<u>200 lks</u>	<u>292 lks</u>	_____

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>w. Pine</u>	<u>Tam</u>	_____
<u>6"</u>	<u>15"</u>	<u>9"</u>	_____
<u>S 20° E</u>	<u>S 88° W</u>	<u>N 62° E</u>	_____
<u>114.82'</u>	<u>145.32'</u>	<u>59.32'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Robert Murray - 1986