


T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 21 Corner common to sections 24 AND 19-142-30



O = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument POST

**Bearing Trees**  
 Species y. Pine y. Pine  
 Diameter 24" 20"  
 Bearing N49E N65W  
 Distance 28 lks 11 lks.

**Original Evidence Found**  
 Year of search 1917 By GLO  
 Monument found none

**Original Bearing Trees Found**  
 Species N. Pine stp N. Pine stp  
 Diameter 20 16  
 Bearing N57E N62W  
 Distance 29 lks 11 lks

**Subsequent Corner Restoration**  
 Year surveyed 1916 By E. B. West  
 Location filed County Book C P. 523  
 Monument Five Stumps of Both Growth B.T.S. SET POST  
- also on microfilm - roll 115 BK 80 P. 42

**Evidence of Subsequent Corner Restoration**  
 Year of search 1917 By GLO  
 Position for corner determined by stumps  
 of B.T.S. - unsafe for corner - W.C. set  
 0.06 chains north - 1" x 36" I.P. w/ Br. Cap.

**Bearing Trees, Reference Objects**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**  
W. Oak N. Pine  
10 10  
N 8 3/4 E N 13 1/2 W  
74 lks 53 lks

**Subsequent Corner Restoration**  
 Year surveyed 1986 By Robert Murray  
 Location filed Corner Certificate - Doc # 296972  
 Monument End 1/2" I.P. that fit bearing's distance  
from 1917 NW Norway Pine B.T.  
set 2" sq x 36" telescope monument w/ stamped  
aluminum cap over 1/2" I.P.  
Norway Pine 11" N60W 26.17'  
Norway Pine 7" S74W 24.77'  
Norway Pine 8" N20E 12.56'  
5' steel sign post N42W 3.0'

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Robert Murray - 1986