


Index No. T5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 114 30 Corner common to sections 29, 30



○ = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>Poplar</u>	<u>B. Oak</u>	
Diameter <u>5</u>	<u>4</u>	
Bearing <u>N 27 W</u>	<u>N 40 E</u>	
Distance <u>18 lks</u>	<u>12 lks</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1915 By JOHN CRO

Location filed COUNTY RESURVEY PLAT E-61

Monument 2 1/4 x 4 1/8" I.M.  
1915, E.B. Hest, Book C P 513 SET CORNER  
also on microfilm - roll 105 BK 60 P. 38

**Evidence of Subsequent Corner Restoration**

Year of search 1915 By S. G. Miller

microfilm - roll 115 BK 83 P. 22  
Misscorner to South on random from east  
BK 83 P. 30 set I.M.

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

1991 Certificate - David Landecker  
Doc # 329607  
Found 2" capped iron pipe up 11". Stamped  
CAP. TIES: 19" N. Pine S64 W 88.40' (1989  
USFS BT), 12" N Pine S1E 37.78' (1989 USFS  
BT), 10" Burr Oak S64 E 46.62' (1989 USFS  
BT).

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_