


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>W. Pine</u>	<u>Birch</u>	
Diameter	<u>30"</u>	<u>3"</u>	
Bearing	<u>S 67 E</u>	<u>N 58 W</u>	
Distance	<u>69 lks</u>	<u>21 lks</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CRO
 Location filed COUNTY RESURVEY PLAT "E-61"
 Monument 2 1/4 x 48" IRON MONUMENT
1915, E. B. HOAST, BOOK "C" P. 511 SET CORNER FROM SE. B.T.
✓ BALDWIN, ✓ P. 514 SET 2 1/4 x 48" I.M.
also on microfilm - roll 105 BK 60 P. 7, 48, P. 80
Set 2 1/4" I.M. with Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1998 By USFS R. MAIN
Found 2" IP, up 8" at NE corner of field.

Bearing Trees, Reference Objects

<u>R. Pine</u>	<u>Maple</u>	<u>W. Oak</u>	<u>Sign Post</u>
<u>24"</u>	<u>9"</u>	<u>7"</u>	
<u>N 63° E</u>	<u>S 83° E</u>	<u>S 62° E</u>	<u>West</u>
<u>72.88'</u>	<u>35.00'</u>	<u>41.80'</u>	<u>3.15'</u>

Subsequent Corner Restoration

Year surveyed 5/01 By Landecker
 Location filed Cass Co. Recorder
 Monument Found 2" IP and 1998 witnesses
Add Cap to IP. A Cert. of Loc. filed.

Lat. 47° 05' 04.1038"
Long. 94° 36' 29.8765"

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared 9/6/01
Filed at Cass Co. Recorder #440136

By T. Freeman
Date _____