

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

143 R. 25 M. 5TH Coordinates: X _____ Y _____
E 143 Corner common to sections 213



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument Post

Bearing Trees

Species	<u>N. PINE</u>	<u>W. PINE</u>	
Diameter	<u>15"</u>	<u>6"</u>	
Bearing	<u>N75E</u>	<u>S24W</u>	
Distance	<u>5LKS</u>	<u>30LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

o = Corner

Subsequent Corner Restoration
 Year surveyed 1908 By JAMES FLYNN
 Location filed COUNTY BOOK "C" P184
 Monument FIND OLD GOVT BT STUMPS; 15" N. PINE
N75E 5LKS, 6" W. PINE STUMP S24W 30LKS
SET POST
1914, EA. DANNER, BOOK "C", P548 FIND 1908 B.T SET 2" IRON
PIN

Bearing Trees, Reference Objects

Species	<u>W. PINE STUMP</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>24"</u>	<u>4"</u>	<u>5"</u>
Bearing	<u>S77E</u>	<u>N 19-36E</u>	<u>S56-45W</u>
Distance	<u>29.0'</u>	<u>119.0'</u>	<u>75.5'</u>
	<u>1908 TIE</u>	<u>1914 TIES</u>	

Evidence of Subsequent Corner Restoration
 Year of search 1971 By Co Hwy Dept
CORD # 74
USGLO Corner replace
22' W. of Q
Reset I.P. in 1974
← 1914 - also on microfilm - roll 115 BX94 P.26-27

Bearing Trees, Reference Objects

C 17

Subsequent Corner Restoration
 Year surveyed 4/5/84 By Co Surveyor, USES
 Location filed _____
 Monument Find 1/2" iron rod W. of Road, S. of
Mail box
also find 1965 ties from Okerman Certificate
20" W. Pine N 30° W 53.29 to PK in B.T.
22" N. Pine S 63° W 80.23 to 1/2" nail
Jan. 1996 L. Pommerening # 17005
Cert. of Sur. Shows iron rod found

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1965
Found Pine stump for 24" W. Pine S77E
29.0'. Set 6" x 24" cylindrical concrete
monument with 3" stamped bronze
tablet 6" below road surface. TIES:
20" W. Pine N30 W 54.2'; 22" N. Pine
S65W 81.2'