

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

143 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 10 Corner common to sections 2, 3, 10, 11



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument Post

Species	Bearing	Trees
<u>FIR</u>	<u>FIR</u>	<u>TAM.</u>
Diameter <u>4"</u>	<u>5"</u>	<u>10"</u>
Bearing <u>N 30 W</u>	<u>N 15 E</u>	<u>S 63 W</u>
Distance <u>20 LKS</u>	<u>18 LKS</u>	<u>30 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1914 By F.A. DENVER
 Location filed Comm 7 Book 2 P. 549
 Monument SET 4x4x48" wood post PROVISIONALY
also on microfilm - roll 115 BK 94 P. 27

Evidence of Subsequent Corner Restoration
 Year of search 1971 By Co Hwy Dept
Co Rd # 74
2" I.M. in place & Rds N-S-E
reset I.P. in 1974

Species	Bearing	Trees, Reference Objects
<u>Aspen</u>	<u>Aspen</u>	<u>B. GILEAD Fence Post</u>
Diameter <u>4"</u>	<u>3"</u>	<u>5"</u>
Bearing <u>N 17-54 W</u>	<u>N 63-34 E</u>	<u>S 63-58 W 537-07 E</u>
Distance <u>144.8'</u>	<u>103.2'</u>	<u>100.0' 44.3</u>

Species	Bearing	Trees, Reference Objects
<u>Poplar</u>	<u>Poplar</u>	<u>Poplar</u>
Diameter <u>10"</u>	<u>10"</u>	<u>6"</u>
Bearing <u>W SW</u>	<u>SW</u>	<u>SSW</u>
Distance <u>103.4'</u>	<u>105.5'</u>	<u>123.1'</u>

E 17

Subsequent Corner Restoration
 Year surveyed 1977 By Co Hwy Dept
 Location filed Schoolcraft State Park Road
 Monument End 2" I.P. in place
10" Pop W 103.3'
8" Pop S W 113.9'
10" Pop S W 123.1'
4/5/84 Co Surveyor, USFS

Evidence of Subsequent Corner Restoration Found
 Year of search 1995 8/14 By L. R. Pommerching
 Found 1 1/2" outside diameter x 24" iron rod, down c. 3'
Left monument as found.
 Monument is on CL N-S Road, 3' S CL Drive E, 3' S
CL Dirt Trail W.
Center of Wood CFP N 41° E 87.58
Center North End 15' 2mi' N 62° 0' 44.18
Center South End 15' 2mi' S 72° 10' 42.73
Center of Telephone Junction Post 5.60° E 127.41'
CA 29-46 Cert. Filed by Kenneth Pommerching, PLS 17005,
Doc. # 375012

End 1 1/2" x 2' steel rod in & N S RD
also ± 10yr old blaze w/ PK in face in
12" Bl/m of Gilead 571 W 100.77'
CFP N 41° E 88.63' 16 d nail
CFP S 19 1/2° E 137.70' 16 d nail
Set U.S.F.S magnet under steel rod

Jan. 1996 L. Pommerching # 17005
Cert. of Sur. Shows iron rod Found