


Index No. V 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 34 Corner common to sections 26, 27, 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>W. OAK</u>	<u>SUGAR</u>	<u>LINDEN</u>
Diameter	<u>16"</u>	<u>4"</u>	<u>6"</u>
Bearing	<u>N64E</u>	<u>N30W</u>	<u>S30W</u>
Distance	<u>5 LKS</u>	<u>10 LKS</u>	<u>7 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1976 By BLM  
Location filed SEC. OF STATE  
Monument SET 2 1/2 x 2 1/2" ALUM POST W/ ALUM CAP TH3N R25W  
527 | 526  
534 | 535  
1976

Evidence of Subsequent Corner Restoration

Year of search 1990 By LANDECKER INC.  
FOUND 2 1/2" ALUM BLM MON 1983 CORRECTIVE  
DEPENDANT RESURVEY OF 1976 SURVEY.  
MON IN MARSH NO TREES AVAILABLE  
SET 8" STEEL SIGN POSTS N 45 W 20.00  
SET STEEL POST 2.03 SOUTH + N 45 E 20.00

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ASPEN</u>	<u>11"</u>	<u>N33E</u>	<u>82 LKS</u>
<u>ASPEN</u>	<u>10"</u>	<u>N16W</u>	<u>68 LKS</u>
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERT BY LANDECKER 1990  
DOC. # 325273

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_