


T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
M.C. # 35 Corner common to sections 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SPRUCE
Diameter 10"
Bearing N67W
Distance 25 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument FND ITASCA CO. ALUM. MON. 2" DIA. W/ALUM. CAP

T143N
S361

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species CEDAR
Diameter 12"
Bearing N51W
Distance 104 1/2 LKS
ITASCA Co. TIE

1
M.C.
R 25
1975

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____