


T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13 and 7, 18-143-25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| | | | | |
|----------|--------------|----------------|----------------|--------------|
| Species | <u>BIRCH</u> | <u>N. PINE</u> | <u>W. PINE</u> | <u>FIR</u> |
| Diameter | <u>6"</u> | <u>6"</u> | <u>8"</u> | <u>8"</u> |
| Bearing | <u>S48E</u> | <u>S63W</u> | <u>N43W</u> | <u>N32E</u> |
| Distance | <u>10CKS</u> | <u>11LKS</u> | <u>21LKS</u> | <u>14LKS</u> |

Original Bearing Trees Found

| | | | | |
|----------|-------|-------|-------|-------|
| Species | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument SET 24" COPPERWELD 6" BELOW SURFACE

Evidence of Subsequent Corner Restoration

Year of search 1990 By Wm. OSUFSEN
END 24" COPPERWELD MON BY BLM

T147N
R26W R25W
S12 S7
S13 S18
BLM
1976

Bearing Trees, Reference Objects

| | | | |
|----------|---------------------------|---------------------------|-------|
| Species | <u>ALUMINUM POST W/CR</u> | <u>ALUMINUM POST W/CR</u> | _____ |
| Diameter | <u>2 1/2 x 28"</u> | <u>2 1/2 x 28"</u> | _____ |
| Bearing | <u>N65E</u> | <u>N52W</u> | _____ |
| Distance | <u>37.3'</u> | <u>94.0'</u> | _____ |

Bearing Trees, Reference Objects

| | | |
|----------|----------------|----------------|
| Species | <u>RED OAK</u> | <u>P. PINE</u> |
| Diameter | <u>12"</u> | <u>10"</u> |
| Bearing | <u>S66E</u> | <u>S89°W</u> |
| Distance | <u>41.23*</u> | <u>68.24*</u> |

* distance to 20d spike

J25

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO
Location filed CCSO
Monument Found copperweld monument
Flush in road, 2' W. of & CR #158,
Also 1976 & 1990 witnesses.
Lower monument to 0.6' below road.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. Wm. OSUFSEN 1990
Doc. # 319113

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____