


T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 13 Corner common to sections 13 AND 18 - 143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	
Diameter	<u>8"</u>	<u>6"</u>	
Bearing	<u>S 76 E</u>	<u>S 58 W</u>	
Distance	<u>10 LKS</u>	<u>6 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1976 By BLM

Location filed SEC. OF STATE

Monument SET 24" COPPERWELD 6" BELOW SURFACE W/ COPPER CAP
T143N
R26W R25W
1/4

Bearing Trees, Reference Objects

Species	<u>ALUM. MON.</u>	<u>ALUM. MON.</u>	<u>513/518</u>
Diameter	<u>2 1/2 x 28"</u>	<u>2 1/2 x 28"</u>	<u>BLM</u>
Bearing	<u>S 70 E</u>	<u>N 15 W</u>	<u>1976</u>
Distance	<u>32.3'</u>	<u>133.4'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSUFSON

FAD COPPERWELD MON BY BLM IN
1976

Bearing Trees, Reference Objects

Species	<u>WHITE OAK</u>	<u>WHITE OAK</u>	
Diameter	<u>8"</u>	<u>12"</u>	
Bearing	<u>N 56 W</u>	<u>N 59 E</u>	
Distance	<u>109.08</u>	<u>47.97</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. WM. OSUFSON 1990
Doc # 319615

Apr. 15, 2002 - Set 18" Telspar with alum. cap, down 0.4", from witnesses. Replace monument destroyed by road maint. B. Hippen T. Anderson