


Index No. L9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 17 Corner common to sections 16, 17



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Bearing Trees

Species	<u>SPRUCE</u>	<u>SPRUCE</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>S82E</u>	<u>N34W</u>	_____
Distance	<u>1145</u>	<u>1215</u>	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By GLO

Location filed Sec. of State

Monument Set 2x36" 1/4" w/ brass cap 1/4
S17/S16
1922

Evidence of Subsequent Corner Restoration

Year of search 1959 By DNR-Engineering

Map notes in file

Found brass cap at P.I. fences
N-S-W

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Poplar</u>	_____
Diameter	<u>8"</u>	<u>12"</u>	_____
Bearing	<u>S54-45E</u>	<u>S12-36W</u>	_____
Distance	<u>23445</u>	<u>18245</u>	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1968

Found GLO monument in good condition
4x4x12" Cedar Post East 3.8'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____