


T. 143 R. 26 M. 5TH Coordinates: X 24 Y 19-143-25
E114 24 Corner common to sections 24 And 19-143-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species TAM. CEDAR
Diameter 6" 6"
Bearing N15 1/2 E N37W
Distance 6 LKS 4 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument SET 2 1/2 x 28" ALUM POST w/ALUM CAP T143N
R26W R26N
1/4
524/519
1976

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSVESEN
FIND 2 1/2 x 28" ALUM. POST w/ALUM CAP SET
IN 1976 BY BLM
STEEL SIGN POST 4.0 NORTH

Bearing Trees, Reference Objects

Species CEDAR CEDAR
Diameter 6" 8"
Bearing N46E N40W
Distance 2 LKS 17 1/2 LKS

Bearing Trees, Reference Objects

CEDAR CEDAR CEDAR
8" 6" 4"
N40 W N46E S71E
11.60 13.97 20.49

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
COR. By WM. OSVESEN 1990
DXX # 319618