


T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 114 25 Corner common to sections 25 AND 30 - 143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species TAM ASPEN  
Diameter 10" 14"  
Bearing S70E S81W  
Distance 1445 1115

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1976 By BCM  
Location filed SEC OF STATE  
Monument SET 2 1/2 X 28" ALUM POST W/ALUM CAP T143N  
R26W R26W  
1/4  
S25/S30  
1976

Bearing Trees, Reference Objects  
Species BIRCH  
Diameter 4"  
Bearing N18W  
Distance 4815

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSUFSEN  
FND NO EVIDENCE OF 1976 BCM MON. OR  
BT. SET 2 X 54" BR/CAP OVER 8' STEEL SIGN  
POST IN SWAMP

SET 8' STEEL SIGN POST 3.5 NORTH

Bearing Trees, Reference Objects  
BIRCH MAPLE BIRCH  
10 7 10  
N54W N61E S63E  
57.90 96.26 84.90

Subsequent Corner Restoration T-25

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERT. BY WM. OSUFSEN 1990  
DOC # 3251410