


T. 143 R. 27 M. 574 Coordinates: X _____ Y _____
N14 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Tam Tam
Diameter 10" 10"
Bearing S6E N42W
Distance 48 LKS 76 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed ? By GEO. RALPH
Location filed COUNTY SURVEY RECORD BOOK B P. 97
Monument FIND OLD POST - OLD B.T. 6" ASH 538-30 W
47.6'

Evidence of Subsequent Corner Restoration
Year of search 1925 By CO. HWY DEPT
State Rd # 4 BOOK 154 PAGE 19
APPROX. corner

also on microfilm - roll 115 BK 82 P. 38

Bearing Trees, Reference Objects
Species Poplar
Diameter 6"
Bearing N37-30W
Distance 41.8'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search 1999 By L. LEUELLING
Set a 9 1/2" x 24" galv. steel pipe w/ brass
cap at the position of a Co. wooden
hub in the 1/4 of C.R. 135 and 9.8"
below grade.

REF: TIES:

18" W. Oak N 2° E 78.71' (23.991m)
Steel sign post South 32.99' (10.056m)
7" Aspen N 62° W 46.26' (14.100m)
395' to W. Culv.
150' to E. Culv.

CERT. OF LOCATION 5-30-99
DOC. NO. 413416