


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	<u>Spruce</u>	<u>Spruce</u>	<u>Spruce</u>	<u>Cedar</u>
Diameter	<u>7"</u>	<u>5"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>S71W</u>	<u>N79W</u>	<u>N31E</u>	<u>S58E</u>
Distance	<u>12LKS</u>	<u>7LKS</u>	<u>22LKS</u>	<u>25LKS</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed ? By GEO RALPH
 Location filed COUNTY SURVEY RECORD BOOK B' P. 97
 Monument FIND POST - OLD B.T CUT DOWN

Evidence of Subsequent Corner Restoration Found
 Year of search 1925 By COURT DEPT
State RD #4 BOKE 154 PAGE 21

also on microfilm - roll 115 BK 82 P. 38

Species	Bearing Trees, Reference Objects			
	<u>CEGAR</u>	<u>TAM</u>	<u>SPRUCE</u>	<u>SPRUCE</u>
Diameter	<u>6"</u>	<u>4"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S44E</u>	<u>S22E</u>	<u>N44W</u>	<u>N36-30E</u>
Distance	<u>50'</u>	<u>41'</u>	<u>50.9'</u>	<u>56.3'</u>

Species	Bearing Trees, Reference Objects	
	<u>Tam</u>	<u>Cedar</u>
Diameter	<u>4"</u>	<u>6"</u>
Bearing	<u>SW</u>	<u>SE</u>
Distance	<u>41.0'</u>	<u>50.0'</u>
	<u>6LO BT</u>	<u>6LO BT</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search 1999 By L. Leuelling RLS 16089
Set a 6" x 24" galv. steel pipe w/ brass cap at E co RD. 135 & proportioned. This perpetuates the original cor. find. by Mr. George Ralph (1910-1915) of Cass Co.
- REF. TIES:
 Std. Sign Post N 44°W 43.70' (to flange)
 " " " N 27°E 39.32' (to flange)
 10" Tamarack S 72°E 154.39'
 P. Pole S 63°W 124.28'

CERT. OF LOCATION 5/17/99
DOC. # 412845