


Index No. R 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Bearing		Trees	
Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>5"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N50W</u>	<u>S40W</u>	<u>S20E</u>
Distance	<u>15 LKS</u>	<u>16 LKS</u>	<u>11 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1999 By L. LEWELLING (NLSM)
Set a 3/4" x 5' alum. rod w/ 3/4" Alum. stamped cap
CERT. OF LOCATION 5-30-99
DOC. NO. 413420

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Tamarack</u>	<u>Tam.</u>	<u>Tw. Cedar</u>	<u>Cedar</u>
<u>9"</u>	<u>8"</u>	<u>8"</u>	<u>7"</u>
<u>N39°E</u>	<u>S36°E</u>	<u>S57°W</u>	<u>N52°W</u>
<u>38.63'</u>	<u>31.88'</u>	<u>3.05'</u>	<u>58.96'</u>
<u>(11.774m)</u>	<u>(9.716m)</u>	<u>(0.930m)</u>	<u>(17.972m)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____