

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| | | | |
|----------|--------------|--------------|-------|
| Species | <u>Cedar</u> | <u>Cedar</u> | _____ |
| Diameter | <u>10"</u> | <u>15"</u> | _____ |
| Bearing | <u>S11W</u> | <u>N68W</u> | _____ |
| Distance | <u>8LKS</u> | <u>10LKS</u> | _____ |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD BOOK "A" P 542-543
Monument FIND OLD CORNER BITS; DOWN 10" CEDAR S11W
8 LKS, 15" CEDAR N68W 10 LKS, SET STAKE
1915, JOHN CURR BOOK "B" P 455-462 FIND TODD'S
N.W. BIT.

Evidence of Subsequent Corner Restoration

Year of search 1998 By NKSEM RLS #16089
Set a 2" x 24" galv. steel pipe w/ brass
cap, 6.5' S. of ♀.

Bearing Trees, Reference Objects

| | | | |
|----------|-----------------|-----------------|-----------------------------|
| Species | <u>TAM STUB</u> | <u>TAM STUB</u> | <u>also on microfilm -</u> |
| Diameter | <u>10"</u> | <u>10"</u> | <u>roll 115 BK 79 P. 30</u> |
| Bearing | <u>N61-45W</u> | <u>N6-26W</u> | _____ |
| Distance | <u>45.60'</u> | <u>52.90'</u> | _____ |

Bearing Trees, Reference Objects

| | | | |
|----------------|---------------|---------------|------------------|
| <u>Cedar</u> | <u>Ash</u> | <u>Ash</u> | <u>Steel</u> |
| <u>7"</u> | <u>6"</u> | <u>9"</u> | <u>Sign Post</u> |
| <u>S18°W</u> | <u>S19°E</u> | <u>N8°E</u> | <u>S5°W</u> |
| <u>150.73'</u> | <u>66.38'</u> | <u>67.10'</u> | <u>50.20'</u> |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____