

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. R7 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument lost

Bearing Trees
 Species Birch Birch
 Diameter 10" 8"
 Bearing S30E N28E
 Distance 10LKS 13LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1928 By GLO
 Location filed Sec. of State
 Monument from testimony of local residents - set w.c.
0.40 CH West - set 1x3/8" I.P. w/brass cap w.c.
4 529
32
1928

Bearing Trees, Reference Objects
 Species white Tam
 Diameter 14" 3"
 Bearing S89E N3W
 Distance 174LKS 31LKS

Evidence of Subsequent Corner Restoration
 Year of search 1970 By William Okerman
Set 60" galvanized steel pipe with
brass cap.

Bearing Trees, Reference Objects
 Cedar Cedar Cedar
 7" 8" 7"
 N42W 570W 528W
 45.00' 39.40' 46.60'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - BOY RIVER
DONALD CHILDS ?

PLAT - RAILROAD ADDITION TO BOY RIVER
JAS. H. FLYNN 1920

1975 Certificate - William Okerman
Doc # 223549

1998 - J. FOSTER (NLSM)
Find 1970 USDA - F.S. concrete mon.
perpetuating the GLO witness to the
1/4 COR. Find 5/8" rebar @ 1/4 cor. POSITION
WITNESS CORNER
REF. TIES:
 15" W. Pine snag S 89° E 113.90' (34.718m)
 9" Cedar S 28° W 46.22' (14.088m)
 8" Cedar S 70° W 39.38' (12.002m)
 St. signpost West 1.60' (0.488m)
(USFS sign 54-4)
 8" Cedar N42° W 45.07' (13.736m)
CERT. OF LOC. 6-2-99
DOC. NO - 413583