


Index No. X 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
E 1/4 34 Corner common to sections 34, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>6"</u>	<u>5"</u>	_____
Bearing	<u>S65W</u>	<u>S72E</u>	_____
Distance	<u>12 LKS</u>	<u>9 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By Laverne Leuelling
Find no evidence of existing corner so
Set 3/4" (.019m) alum. rod w/ alum. stamped
cap, up 0.6' above grd.

REFERENCES:

6" Ash N 24° W 20.98' (6.396m)
8" Balsam S 68° W 45.79' (13.958m)
9" Balsam S 22° E 12.93' (3.940m)
(F.S. 54") Std. Sign Post N 89° W 1.18' (0.360m)
CERT. OF LOCATION FILED 5/25/99
DOC. # 413184

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____