


Index No. G 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E114 12 Corner common to sections 12 AND 7-143-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar Poplar  
Diameter 10" 14"  
Bearing S85W N40E  
Distance 6 LKS 12 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed ? By Geo. Ralph  
Location filed County Survey Return Book B' 894-95  
Monument Find Geo. Govt B.T.S. - Rotten Stumps: Poplar  
N 90°W 44', Poplar N 76° E 8'

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept  
State RD #4  
Corner

also on microfilm - roll 115 BK 82 P. 31

Bearing Trees, Reference Objects

Species BIRCH BIRCH  
Diameter 10" 10"  
Bearing N64-30W N85E  
Distance 42.6' 64.8'

Bearing Trees, Reference Objects

Birch Birch Stump  
10" 10"  
SW NW  
42.6' 64.8'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_