

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
E 14 13 Corner common to sections 13 AND 18-143-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Poplar Poplar
Diameter 8" 14"
Bearing N22E S40W
Distance 11LKS 21LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed ? By Geo. Rauch
Location filed Cass Co Survey Record Book B P 94-95
Monument Find old post - old B.T. STUMPS: S44-30W
13', N55-30E 13'

Evidence of Subsequent Corner Restoration

Year of search 1925 By To. Hwy Dept
State Rd #4
Corner

also on microfilm - roll 115 BK 82 P. 32

Bearing Trees, Reference Objects

Species ASH BIRCH
Diameter 10" 12"
Bearing N79W S87-30E
Distance 42.4' 4.5'

Bearing Trees, Reference Objects

Birch Ash
12" 10"
SE NW
45.0' 42.4'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Walter Curo
Doc. # 291480
Set 2" x 24" galvanized iron pipe with
brass cap 1" below surface of Co Rd 4.
11" W. Oak N80E 94.65"
5" Aspen S70E 69.62"
7" Balsam S36W 121.06"

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____