


T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 5 Corner common to sections 4, 5 AND 32, 33 -144-31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Dead Tam</u>	<u>Dead Tam</u>	<u>Dead Tam</u>	<u>Dead Tam</u>
Diameter	<u>3"</u>	<u>3"</u>	<u>2 1/2"</u>	<u>3"</u>
Bearing	<u>N 49 W</u>	<u>N 54 W</u>	<u>S 58 W</u>	<u>S 52 W</u>
Distance	<u>95 LKS</u>	<u>100 LKS</u>	<u>55 LKS</u>	<u>59 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURE  
Location filed COUNTY RESURVEY PLAT 'E-66"  
Monument CEDAR POST  
1915, CURE, BOOK "C" P. 487 AND BOTH N.W. BT'S AND OLD STAKE

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO  
Find all 4 Govt B.T.S. down Set 2 X 36" I.P.W. Brass cap

7144N  
R 31 W  
532 / 533  
55 / 54  
7143N  
1919

Bearing Trees, Reference Objects

Species CEDAR POST  
Diameter 4"  
Bearing N 52 W  
Distance 65.60'

Bearing Trees, Reference Objects

in bag - no B.T.S.

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_