

Distance
Bearing
Diameter
Species

Bearing Trees, Reference Objects

Monument

Year surveyed
Location filed

By

Subsequent Corner Restoration

Distance
Bearing
Diameter
Species

Bearing Trees

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

Coordinates: X 114 R 25 M 5TH
Corner common to sections 114

CASS COUNTY LAND CORNER RECORD

Index No. 519

Subsequent Corner Restoration


Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set obliterated from 1900 Corp's info - set
5/8" X 10' aluminum rod w/cap
4" Tamarack N 20° W 13.40'
4" Spruce S 45° W 16.23'
Doc. # 281712

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____



Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Year of search _____ By _____
Monument found _____

Original Evidence Found

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Distance
Bearing
Diameter
Species